



---

# SERVICE BULLETIN

---

Classification:

EC11-027

Reference:

NTB11-097

Date:

October 21, 2011

---

## INTAKE AIR VOLUME LEARN WILL NOT COMPLETE

APPLIED VEHICLES:

All

APPLIED DATES:

2007 - 2012

### SERVICE INFORMATION

If IAVL will not complete using CONSULT:

- a. While the engine is running, disconnect "Mass Air Flow" (MAF) sensor for 10-15 seconds until MIL (P0102 or P010C) comes on, and then reconnect **before** performing "Intake Air Volume Learn" (IAVL).
  - If vehicle has two MAF sensors, disconnect **only one** in prior step and leave the second one connected; then reconnect.
  - Engine may stop running when idle reduction occurs. Reconnect MAF sensor and continue to step "b".

**NOTE:** If P0102 or P010C were not stored when DTC was confirmed, repeat step "a" until idle is reduced.

- a. Clear any DTC's that may have set during MAF disconnect.
- b. Perform IAVL.
- c. Confirm that idle is now within specification for model and year of vehicle being worked on.

See Electronic Service Manual for procedure to set IAVL and for vehicle idle specifications.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.