



---

# SERVICE BULLETIN

---

Classification: EL10-021a	Reference: NTB10-061a	Date: June 29, 2010
------------------------------	--------------------------	------------------------

---

## XENON HEAD LAMP SERVICE

This bulletin has been amended. The Parts Information has been updated.  
Please discard previous versions of this bulletin.

**APPLIED VEHICLES:** 2005 – 2010 Nissan with xenon headlamps

### IF YOU CONFIRM

A xenon headlamp is not functioning because of an issue inside the headlamp assembly (an internal issue),

### ACTION

Refer to the appropriate Service Manual, follow the diagnostic and repair information for xenon headlamps.

#### NOTE:

- In most cases, replacement of a bulb or HID control unit will solve the incident.
- **Do not replace the entire xenon headlamp assembly when a bulb or HID control unit is available to solve the incident, if one should occur.**

### CLAIMS INFORMATION

- Reference the current Nissan Flat Rate Manual and use the appropriate claims coding for the repair performed.
- For HID control unit replacement, use Operation Code RJ36AA.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## PARTS INFORMATION

DESCRIPTION	MODEL	YEAR	PART NUMBER	QTY
HID Control Unit (Includes Starter)	Altima (L32)	2007 – 2010	28474 - 8991B	1 per side as needed
	Maxima (A34)	2005 – 2008		
	Maxima (A35)	2009 – 2010		
	Rogue (S35)	2008 – 2010		
	350Z (Z33)	2003 – 2009		
	370Z (Z34)	2009 – 2010		
	Murano (Z50)	2003 – 2007		
	GT-R (R35)	2009 – 2011		
	Murano (Z51)	2009 – 2010	28474 - 8992A	
	Altima (L31)	2005 – 2006	26055 - 8J100	
Xenon Headlamp Bulb	Altima (L32)	2007 – 2010	26297 - 9B91A	1 per side as needed
	Maxima (A34)	2005 – 2008		
	Maxima (A35)	2009 – 2010		
	350Z (Z33)	2003 – 2009		
	370Z (Z34)	2009 – 2010		
	Murano (Z50)	2003 – 2007		
	Murano (Z51)	2009 – 2010		
	GT-R (R35)	2009 – 2011		
	Rogue (S35)	2008 – 2010	26297 - 9B90A	
	Altima (L31)	2005 – 2006	26297 - 89910	

### NOTE:

- The HID control unit includes a starter (xenon bulb socket). For some models, the starter is not replaceable. In this case, replace only the HID control unit using the old starter.
- Torque specification for the screw that holds the starter to the HID control unit is:  
1.3 – 1.7 N•m (0.13 – 0.17 k-gm, **12 – 15 in-lb**)

