



---

# SERVICE BULLETIN

---

Classification:

RS00-003b

Reference:

NTB00-042b

Date:

February 15, 2011

---

## RECOMMENDATION AGAINST MAKING CHANGES TO FRONT SEAT ASSEMBLY TRIM MATERIALS

<p>This bulletin has been amended. The Applied Vehicles and Service Information have been updated. Discard all previous copies.</p>
---

**APPLIED VEHICLES:** ALL NISSAN VEHICLES

### SERVICE INFORMATION

Changes or modifications to the front seat assembly trim materials may affect the proper operation of the Front Seat-Mounted Side-Impact Supplemental Air Bags and Passenger Occupant Classification Sensor and could result in serious personal injury or death.

Nissan **STRONGLY RECOMMENDS AGAINST** making any change to seat trim materials from the factory equipped condition. This specifically applies to replacing the seat trim with non-factory materials; adding leather/cloth seat covers, seat pads, or seat storage pouches, etc. around or over the seat back and the passenger seat cushion.

- Damage or failure due to changes or modifications to the front seat assembly are not covered under the warranty.
- Damage or failure due to changes or modifications to the front seat assembly are not subject to indemnification under the Nissan Dealer Sales and Service Agreement.
- Dealers may be obligated under their Nissan Dealer Sales and Service Agreement to indemnify Nissan for any damages, injuries, or deaths caused by modification of the front seat assemblies.
- NMAC will not provide retail advance for any changes to the front seat trim materials from factory equipped condition.
- Vehicles with any changes to the front seat trim materials from factory equipped condition may not be eligible for the **Signature PURCHASE Plan**.

SEE Section 1 of the applicable Owner's Manual for important Warnings and other information about Front Seat-Mounted Side-Impact Supplemental Air Bags and Passenger Occupant Classification Sensor.