



SERVICE BULLETIN

Classification: EC09-007	Reference: NTB09-029	Date: April 21, 2009
-----------------------------	-------------------------	-------------------------

CONSULT-III ECM REPROGRAMMING PROCEDURE

APPLIED VEHICLES: All CONSULT-III (C-III) compatible Nissan vehicles

SERVICE INFORMATION

A complete step-by-step General Procedure for C-III ECM Reprogramming is now available by hyperlink in this bulletin.

This General Procedure is also available via hyperlink from specific C-III symptom-based Technical Service Bulletins in ASIST.

Click → [HERE](#) ← to view instructions for the entire General Procedure.

CAUTION: BEFORE STARTING REPROGRAMMING

- Connect a battery charger to the vehicle battery.
If the 12V battery voltage drops during reprogramming, the ECM may be damaged.
- Be sure to turn OFF all vehicle electrical loads.
If a vehicle electrical load remains ON, the ECM may be damaged.
- For ECM reprogramming, the C-III MUST be connected to the VI using the USB cable.
- Be sure to connect the AC Adapter.
If the C-III battery voltage drops during reprogramming, the process will be interrupted and the ECM will be damaged.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.