



SERVICE BULLETIN

Classification: WT10-001b	Reference: NTB10-048b	Date: October 3, 2011
------------------------------	--------------------------	--------------------------

SIGNAL TECH II DIAGNOSTIC TOOL

This bulletin has been amended. The note below APPLIED VEHICLES was amended. Please discard previous versions of this bulletin.

APPLIED VEHICLES: All Nissan with Tire Pressure Monitor System (TPMS), Remote Keyless Entry, or Intelligent Key.

NOTE: Failure to update Signal Tech II may lead to misdiagnosis of certain models.

- The latest software is available on the CONSULT III PC at: ASIST > Specialty Tools > Signal Tech II
- If you should encounter problems updating Signal Tech II, contact Techmate at 1-800-662-2001.
- Future updates will be released as needed. Check ASIST frequently for this information.

SERVICE INFORMATION

If service is required on a vehicle's Tire Pressure Monitor System (TPMS), remote keyless entry, or Intelligent Key, the Signal Tech II (special tool J-50190) can be used for diagnostics.

Signal Tech II will quickly:

- Activate and display TPMS Sensor IDs
- Display tire pressure reported by the TPMS sensor
- Read TPMS DTCs and register TPMS IDs
- Store and print reports for warrantable repairs
- Check Intelligent Key relative signal strength
- Test remote keyless entry relative signal strength
- Confirm vehicle Intelligent Key antenna relative signal strength output
- Read ENGINE DTCs



Other available information for Signal Tech II:

- Signal Tech II Quick Start Guide: ASIST > Tools & Equipment > Tool & Equipment Web Page
 - Signal Tech II Users Guide: ASIST > Tools & Equipment > Tools & Equipment Web Page
 - Tool Flyer: ASIST > Tools & Equipment > Tools & Equipment Web Page > Nissan Essential Tool Flyers
 - Tech Talk Article: ASIST > Tech Support Info > TECH TALK / XTRA > Spring 2010 issue
-